

Energy Conservation Flywheel
With Variable Moment

Of Inertia (ECF-VMI) Model: ECF-VMI-01 Inventor: Velimir Mike Stanimirovic, P.E. Telephone: 305-754-0749/305-759-1765

Application #10/788,647






Energy Conservation Flywheel With Variable Moment Of Inertia (ECF—VMI) Model: ECF—VMI—01

Telephone: 305-754-0749/305-759-1765 Application #10/788,647

Inventor: Velimir Mike Stanimirovic,


نب ک



Energy Conservation⁽ lywheel With Variable Moment Of Inertia (ECF—VMI) Model: ECF—VMI—01

Inventor: Velimir Mike Stanimirov., P.E. Telephone: 305-754-0749/305-759-1765

Application #10/788,647





ENERGY CONSERVATION FLYWHEEL

WITH VARIABLE MOMENT OF INERTIA (ECF-VMI)

MODEL: ECF-VMI-01

INVENTOR: VELIMER MIKE STANIMIROVIC, P.E. TELEPHONE: 305-754-0749/305-759-1765

NAME OF PARTS (COMPONENTS)

- STEEL FRAME (SF), SUB-ASSEMBLY (ONE REQ.) 1.
- STEEL SPHERE (SS), SOLID STEEL (FOUR REQ.) 2.
- WHEEL/DISK (W/D), STEEL (ONE REQ.)
- PISTON/ROD (PI/R), STEEL-FINE MACHINED (FOUR REQ.)
- HOLLOW SHAFT (HS), STEEL-FINE MACHINED (ONE REQ.)
- STEEL SPRING (SSP), EXTENSION SPRING (ONE REQ.) 6.
- 7. STEEL CABLE (SC), STAINLESS STEEL (FOUR REQ.)
- 8. BALL BEARING-UPPER-(BBU), STEEL (ONE REQ.)
- BALL BEARING-LOWER-(BBL), STEEL (ONE REQ.)
- 10. BALL BEARING-BOTTOM- (BBB), (ONE REQ.)
- 11. TENSION BOLT AND NUT (TBN) (WITH SPRING WASHER), STAINLESS STEEL (ONE REQ.)
- 12. STEEL CABLES CLIP (SCC), STEEL (ONE REQ.)
- 13. SHAFT COLLAR (SCO), STEEL (ONE REQ.)
- 14. STOP PIN (SP), STAINLESS STEEL (FOUR REQ.)
- 15. SET SCREW FOR CABLE (SSC), STAINLESS STEEL (FOUR REQ.)
- 16. BEARING FASTENING BOLTS (BFB), STEEL (EIGHT REQ.)
- 17. FLEXIBLE COUPLING AND/OR CLUTCH (FCC), ALUMINUM (ONE REQ.)
- 18. SET SCREW (SCR), STEEL (AS REQ.)
- 19. SUPPORTING LEG LOWER (4 REQ.)
- 20. SUPPORTING LEG UPPER (2 REQ.)
- 21. STEEL PLATE #1 (ONE REQ.)
- 22. STEEL PLATE #2 (ONE REQ.)
- 23. STEEL PLATE #3 (ONE REQ.)
- 24. BOLT WITH SPRING WASHER (TWO REQ.)
- 25. BOLT FOR LEVEL ADJUSTMENT (FOUR REQ.)
- 26. BOTTOM SUPPORT LEG (FOUR REQ.)
- 27. BOLT WITH SPRING WASHER (TWO REQ.)